

Typical 3-S Setup Configurations

ARC•ER Head can be used with other machine tools. It has a 1/2" x 2" straight shank arbor that can be secured in a 3 point chuck or 1/2" end mill holder or one of our magnetic fixtures.

